

Waterloohain 5, 22769 Hamburg, Germany www.trinamic.com February 18, 2015

Dear Valued TRINAMIC Customer,

this is to inform you that a new firmware **V1.08** version has officially been released for the module

TMCM-1110

The module will be delivered together with this new release. Modules already shipped can be updated to this new release using the firmware update feature of the TMCL-IDE via serial or USB interface. The new firmware and updated documentation will be available for download from the Trinamic website. Prior releases are still available on request. If you have any questions, please contact your sales partner.

Firmware Changes (compared to V1.04):

- Reference search modes 7 and 8 fixed
- Global parameter 79 added
- TMCL command 138 (target reached event) improved
- RFS STATUS command also copies its result into the accumulator register
- Fixed problem in TMCL interrupt handling that could lead to race conditions
- Fixed problem with RS485 (RS485 sometimes did not switch back to receive mode)

This improvement is classified as a minor change.

Products Affected

| Article Name | Affected Article Numbers |
|----------------------|--------------------------|
| TMCM-1110 stepRocker | 10-0239 |

Timing

| Effective date for firmware release | 18.02.2015 |
|-------------------------------------|------------|
|-------------------------------------|------------|