

Dear Valued TRINAMIC Customer,

this notification is to inform you that an additional manufacturing facility, assembly facility, and test facility has been qualified for the

TMC239

TMC249

There is no change in function and the article names and article numbers are unchanged. The additional manufacturing facility is traceable via date code together with lot number. A character 'B' is inserted between date code 'wwyy' and lot number 'lllll' for components assembled and tested at the additional facility: wwyyBlllll, with ww = working week, yy = last two digits of year, character B, lllll = lot number. First affected components have date code 1249.

Products Affected

Article Name	Affected Article Numbers
TMC239A-SA	00-0009
TMC239A-SA-T	00-0009T
TMC239A-SA-X	00-0009X
TMC249A-SA	00-0063
TMC249A-SA-T	00-0063T
TMC249A-SA-X	00-0063X

If you have any questions, please contact your sales partner.